Prüfbericht - Nr.: *Test Report No.:*	**IND/BLR/CH/2018/1500R**	**Seite 1 von 3** *Page 1 of 3*

Auftraggeber: *Client:*	**Sunflex Recycling Pvt ltd** Plot No. – 274/4, Shital Estate B/H Satyamev Complex, Opp. Gujrat High Court, S. G. Highway, Sola Ahmedabad, 380060, India
Gegenstand der Prüfung: *Test item:*	RUBBER Tiles
Bezeichnung: *Identification:*	**Serien-Nr.:** *Serial No./* Document Submitted*:*
Wareneingangs-Nr.: *Receipt No.:*	06032018
Order No.:	1803301976
Eingangsdatum: *Date of receipt:*	06.03.2018
Testing Period:	12.03.2018 to 18.03.2018
Prüfort: *Testing location:*	TÜV Rheinland India Pvt Ltd, Plot No. 27/B, 2nd Cross Road, Electronics City , Phase 1, Bangalore - 560 100, Karnataka, India.
Prüfgrundlage: *Test specification:*	Customer's Requirement : Burning Behaviour Test as per FMVSS 302
Prüfergebnis: *Test Result:*	Refer Page No.2 to 3

Prüflaboratorium/ Testing Laboratory:

zusammengestellt/ *compiled by*:			**kontrolliert/** *checked by*:		
20.03.2018	Ranabir Pal Manager - Polymer Section, Material Testing Laboratories, Industry Services		20.03.2018	Rajesh Jain B Technical Head, Material Testing Laboratories, Industry Services	
Datum *Date*	**Name** *Name*	**Unterschrift** *Signature*	**Datum** *Date*	**Name** *Name*	**Unterschrift** *Signature*

Sonstiges/ Other Aspects: Report has been revised to update sample name as requested by client

Abkürzungen:	***ok / P***	***= entspricht Prüfgrundlage***	***Abbreviations:***	***ok / P***	***= passed***
	fail / F	***= entspricht nicht Prüfgrundlage***		***fail / F***	***= failed***
	n.a. / N	***= nicht anwendbar***		***n.a. / N***	***= not applicable***

Dieser Prüfbericht bezieht sich nur auf das o.g. Prüfmuster und darf ohne Genehmigung der Prüfstelle nicht auszugsweise vervielfältigt werden. Dieser Bericht berechtigt nicht zur Verwendung eines Prüfzeichens.

This test report relates to the a. M. Test sample. Without permission of the test center this test report is not permitted to be duplicated in extracts. This test report does not entitle to carry any safety mark on this or similar products. Test item submitted by client. Sampling not done by TUVRI

TEST RESULTS

Sample Photograph as in Received Condition

Test Name: Burning Behaviour Test

Test Method: FMVSS 302

Test Conditions: Pre-Conditioning – At 23±2°C, 50±5%RH for 24 hrs.
Lab Environmental condition - 23±2°C, 50±5%RH

Requirement: 100 mm/min

Sample Photograph During Test

Prüfbericht - Nr.: *Test Report No.:*	**IND/BLR/CH/2018/1500R**	**Seite 3 von 3** *Page 3 of 3*

Observations:

Sr. No.	Classification	Pass/Fail	Burning Rate(mm/min)
1	B	Pass	7.68
2	B	Pass	6.61
3	B	Pass	6.45
4	B	Pass	5.96
5	B	Pass	7.11
Average Burning Rate			**6.8 mm/min**

Conclusion: Tested sample meets the requirement of customer's specification.

---- End of Report ----